











Figure 10 shows a micrograph of a fracture surface. A vertical crack line is visible, separating the material into two parts. On the left side, there is a small, circular feature, possibly a pore or a second phase particle. The surface texture is granular and uneven.